

How to use Skysensor 2000 PC

=====

In order to have 3-star alignment with Skysensor 2000 PC use the following procedure.

1. Set correct location coordinates (longitude-latitude) and time. Do not change to summer time just keep the winter time.
2. Do a rough polar alignment of the scope.
3. Set up mount mode to "Unaligned EQ" with the scope pointing directly west.
4. Pick an alignment star from the Refstar menu.
5. Press "ENTER" to select it.
6. Press "GOTO".
7. Use the hand controller to accurately center the star in the field of view (for best accuracy use an illuminated reticle eyepiece).
8. Press "ENTER" again - this is VERY important and must be done each time you intend to align to an object.
9. Press "ALIGN"
10. Continue until a "3-star alignment" message appears in Skysensor.